









7 Priority sites for Management Intervention

The following sections present the proposed management interventions for each of the sites identified as a priority. For each site a concept design has been prepared for the construction related activities. It is assumed that fencing and revegetation of these sites will be undertaken to support the engineering interventions. It is anticipated that in these locations the extent of fencing and revegetation may be significantly greater than the area immediately surrounding the proposed works locations.

A summary of the symbology used in the concept design sketches is presented in Table 17.


Table 17 Key to concept design plans

Symbol	Reference
	Waterway
	Location of Rock Beaching
	Location of Fencing
	Downstream Waterway
	Location of Rock Chute
	Area proposed for revegetation
	Location for Spillway
	Location for Pile Fields

7.1 Sites with Extreme Risk Ranking


7.1.1 Bank Erosion Lower Buchan Creek (Site 2)

Concept Design:




7.1.2 Gully, Bed & Bank Erosion Buchan Creek (Site 3)

Concept Design:




7.1.3 Channel Deepening Bredbo Gully (Site 4)

Concept Design:




7.1.4 Sediment Transfer Bredbo River Gully (Site 5)

Concept Design:



7.1.5 Bank Erosion Spring Station Creek (Site 20)

Concept Design:



7.1.6 Bank Erosion Lanyon Canyon (Site 34)

Concept Design:



7.1.7 Bank Erosion Murrumbucca Creek (Site 40)


Concept Design:

Construct rock beaching at erosion site




7.1.8 Bed & Bank Erosion Naas River (Site 41)

Concept Design:




7.1.9 Sediment Transport Naas River Tributary (Site 42)

Concept Design:




7.1.10 Bank Erosion Naas River (Site 43)

Concept Design:




7.1.11 Bank Erosion Naas River (Site 45)

Concept Design:



7.1.12 Bank Erosion Tidbinbilla Creek (Site 51)


Concept Design:



7.2 Sites with Very High Risk Ranking


7.2.1 Gully Erosion Stockyard Creek (Site 1)

Concept Design:




7.2.2 Bank Erosion Cooma Creek (Site 18)

Concept Design:




7.2.3 Bank Erosion Lower Gudgenby River (Site 19)

Concept Design:




7.2.4 Bank Erosion Gudgenby River (Site 21)

Concept Design:




7.2.5 Bank Erosion Honeysuckle Creek (Site 23)

Concept Design:




7.2.6 Bank Erosion Murrumbidgee River (Site 38)

Concept Design:



7.2.7 Sediment Transport Naas Tributary Gully (Site 44)

Concept Design:



7.2.8 Bank Erosion Lower Rose Valley (Site 50)

Concept Design:

